

Single Event Gate Rupture Characterization of the Fuji MOSFETs: 2SJ1A03 (A08P10), 2SJ1A09 (A08P20), and NSD1A01

Leif Scheick Jet Propulsion Laboratory Pasadena, California

Jet Propulsion Laboratory California Institute of Technology Pasadena, California

JPL Publication 14-6 01/14



Single-event Gate Rupture Characterization of the Fuji MOSFETs: 2SJ1A03 (A08P10), 2SJ1A09 (A08P20), and NSD1A01

NASA Electronic Parts and Packaging (NEPP) Program
Office of Safety and Mission Assurance

Leif Scheick Jet Propulsion Laboratory Pasadena, California

NASA WBS: 939904.01.11.30 JPL Project Number: 102197 Task Number: 3.23.5

Jet Propulsion Laboratory 4800 Oak Grove Drive Pasadena, CA 91109

http://nepp.nasa.gov

This research was carried out at the Jet Propulsion Laboratory, California Institute of Technology, and was sponsored by the National Aeronautics and Space Administration Electronic Parts and Packaging (NEPP) Program.

Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not constitute or imply its endorsement by the United States Government or the Jet Propulsion Laboratory, California Institute of Technology.

©2014 California Institute of Technology. Government sponsorship acknowledged.

TABLE OF CONTENTS

1.0	Purpose	1
	Test Samples	
	General	
4.0	Electrical Tests	4
5.0	Failure Criteria.	24
6.0	Schedule	25
7.0	Bias Condition/Fixtures	26
	7.1 Setup	26
8.0	Procedure	27
	Results	
10.0	Conclusion and Recommendation	36

1.0 PURPOSE

This testing is to characterize the power MOSFETs listed in Table 1.0-1 for single-event gate rupture (SEGR) and single-event burnout (SEB) response. Test results were compared against comparable voltage rated devices.

Table 1.0-1. List of power MOSFET devices that will be tested for SEE characterization.

Manufacturer	Part Number	Voltage rating (V)	Channel	Number provided	Package
FUJI	2SJ1A03 (11P10)	-100	Р	50	TO-254
FUJI	2SJ1A09 (08P20)	-200	Р	50	TO-254
FUJI	NSD1A01	600	N	50	24 DIP

2.0 TEST SAMPLES

The test samples are outlined in Table 1.0-1. Parts were handled in accordance with all ESD precautions. All parts had the following parameters measure before SEE testing: transconductance, voltage threshold, gate leakage. The following stress tests were applied to all devices: full off gate bias and 80% drain bias. All devices passed these tests and were approved for testing. Table 2.0-1 lists the steps required in preparing and vetting the parts in this test.

Table 2.0-1. List of power MOSFET devices that will be tested for SEE characterization.

Step	Part Numbers	Action	ATE	Serial Number and Calibration end date	Compliance
Check in	All	Verify part number, visually inspect for damage and assign SEE test serial number	NA	NA	Yes
Initial parametric test	All	Measure gm, Vth and Igss @ ±20 V	HP4156		Yes
Initial stress test	All	Apply absolute maximum Vgs (off) and absolute maximum Vds	HP4142		Yes
De-lid and die photo	All	De-lid and die photo	NA	NA	Yes

3.0 GENERAL


Eighteen (18) of the fifty (50) available NSD1A01 have been tested. Thirty six (36) of the fifty (50) available 2SJ1A09 have been tested. Twenty four (24) of the fifty (50) available 2SJ1A03 have been tested. Parts were tested at Brookhaven National Laboratory (BNL) and the Texas A&M University Radiation Effect Facility (TAMU-REF). See Table 3.0-1 for a list of tested parts and ions.


Table 3.0-1. Selected ion beam energy (15 MeV/amu).


Group	Qty	Part Number	Gate to Source Bias [V]	Site	Surface LET [MeV mg/cm ²]	lon-Energy [MeV]	lon (range in Si [μm])
A1	6	2SJ1A03	Vgs= 0, 5, 10, 15, 20	TAM	36	Kr-300	60
A2	6	2SJ1A03	Vgs= 0, 5, 10, 15	BNL	36.1	Br-279	37.45
A3	6	2SJ1A03	Vgs= 0, 5, 10, 15, 20	TAM	61	Xe-648	52.3
A4	6	2SJ1A03	Vgs= 0, 5, 10, 15, 20	TAM	27.1	Kr-1097	144.2
A5	6	2SJ1A03	Vgs= 0, 5, 10, 15, 20	TAM	50.2	Xe-1632	129
B1	6	2SJ1A09	Vgs= 0, 5, 10, 15	TAM	94.4	Au-1768	88.1
B2	6	2SJ1A09	Vgs= 0, 5, 10, 15	TAM	31.5	Xe-333	63.4
B3	6	2SJ1A09	Vgs= 0, 5, 10, 15	TAM	50.9	Xe-1569	124.5
B4	6	2SJ1A09	Vgs= 0, 5, 10, 15	TAM	36	Kr-300	60
B4	6	2SJ1A09	Vgs= 0, 5, 10, 15	BNL	36.1	Br-279	37.45
B5	6	2SJ1A09	Vgs= 0, 5, 10, 15	TAM	27.1	Kr-1097	144.2
C1	3	NSD1A01	Vgs= 0, −5	TAM	84.7	Au-2342	123
C2	3	NSD1A01	Vgs= 0, −5	TAM	94.4	Au-1768	88.1
C3	6	NSD1A01	Vgs= 0, -5, -10, -15	TAM	50.9	Xe-1569	124.5
C4	3	NSD1A01	Vgs= 0, -5, -10	TAM	34.8	Kr-533	64.6
C5	3	NSD1A01	Vgs= 0, -5, -10	TAM	31	Kr-733	96.1
C6	3	NSD1A01	Vgs= 0, -5, -10	TAM	50.2	Xe-1632	129


4.0 ELECTRICAL TESTS


Electrical tests were performed in accordance with "The Test Guideline for Single Event Gate Rupture (SEGR) of Power MOSFETs" [JPL Publication 08-10 2/08]. The threshold voltage (Vth) and transconductance (gm) were measured on all parts prior to irradiation. All parts were in specification. However, the 2SJ1A03 (A08P10) exhibited forward breakdown when the full off-gate-to-source bias (Vgs-off) and full drain-to-source bias (Vds) were simultaneously applied to these devices. Figure 4.0-1 through Figure 4.0-38 present the effect. This phenomenon prevented the post irradiation test of simultaneous full gate and drain stress, which altered the failure criteria in section 5.0. However, this condition did not prevent the biasing conditions required for SEE testing.



































































Figure 4.0-23






































5.0 FAILURE CRITERIA

Failure criteria shall be classified in accordance with "The Test Guideline for Single Event Gate Rupture (SEGR) of Power MOSFETs" [JPL Publication 08-10 2/08]. Due to the 2SJ1A03 (A08P10) not being able to support full off-gate and drain bias, the post irradiation stress test (PIST) was a gate stress of -20 V followed by an application 80% of drain bias for 3 seconds. Out of specification reading during irradiation or either stress test was considered an SEE caused failure.

6.0 SCHEDULE

These tests occurred on February 22, 2012 at BNL and March.23, 2012 at TAM.

7.0 BIAS CONDITION/FIXTURES

Bias condition during the biased irradiations shall be in accordance with "The Test Guideline for Single Event Gate Rupture (SEGR) of Power MOSFETs" [JPL Publication 08-10 2/08]. Unbiased parts shall be exposed in a manner that protects them against ESD.

7.1 Setup

Failure criteria were classified in accordance with "The Test Guideline for Single Event Gate Rupture (SEGR) of Power MOSFETs" [JPL Publication 08-10 2/08]. Figure 7.1-1 shows the setup used in this experiment. An HP4142 forced the voltage and read a current with three independent SMUs. The background current on the board with no DUT was recorded to be ~0.5 nA in each device location. All parts were tested at ambient laboratory temperatures.




Figure 7.1-1. Setup used for SEE testing. Entire system is transported to heavy ion site

8.0 PROCEDURE

General test procedure shall adhere to the "The Test Guideline for Single Event Gate Rupture (SEGR) of Power MOSFETs" [JPL Publication 08-10 2/08]. Parts shall be serialized (if not already done), with controls marked prominently to distinguish them from test samples. Exposures shall be performed at ambient laboratory temperature.

9.0 RESULTS

All of the tests proceeded without anomaly. No latent damage or small breaks were seen, but a majority of the device failures during the post irradiation stress tests, and not during beam irradiation.




Figure 9.0-1. SEE test results of the 200 V Fuji p-channel with Br-279 at BNL. These data are comparable to results from similar ions at TAM (cf. Figure 9.0-2)




Figure 9.0-2. SEE test results of the 200 V Fuji p-channel with Kr-300 at TAM. These data are comparable to results from similar ions at BNL (cf. Figure 9.0-1). Note that at Vgs=-5 V, no SEE occurred and this effect is under investigation.




Figure 9.0-3. SEE test results of the 100 V Fuji p-channel with Br-279 at BNL. These data are comparable to results from similar ions at TAM (cf. Figure 9.0-4)




Figure 9.0-4. SEE test results of the 100 V Fuji p-channel with Kr-300 at TAM. These data are comparable to results from similar ions at BNL (cf. Figure 9.0-3).




Figure 9.0-5. SEE test results of the 200 V Fuji p-channel with Au-1768 at BNL.




Figure 9.0-6. SEE test results of the 100 V Fuji p-channel with Xe-648 at TAM.




Figure 9.0-7. SEE test results of the 200 V Fuji p-channel with Xe-333 at TAM.




Figure 9.0-8. SEE test results of the 600 V Fuji n-channel with Kr-533 at TAM.




Figure 9.0-9. SEE test results of the 600 V Fuji n-channel with Xe-1220 at TAM.




Figure 9.0-10. SEE test results of the 200 V Fuji p-channel with Xe-1569 at TAM.




Figure 9.0-11. SEE test results of the 600 V Fuji n-channel with Kr-733 at TAM.




Figure 9.0-12. SEE test results of the 600 V Fuji n-channel with Au-2342 at TAM.




Figure 9.0-13. SEE test results of the 600 V Fuji n-channel with Au-1768 at TAM.

10.0 CONCLUSION AND RECOMMENDATION

These parts are comparable to similarly rated non-SE-hardened devices. However, the observations that the gate rupture occurred on the stress test as opposed to during the irradiation will require that testing of these devices employ the stress test for part assurance.

			REPORT DOCUMEN	NTATION PAG	E		Form Approved OMB No. 0704-0188		
existing data s estimate or an Services, Direct be aware that display a curre	ources, gathering a y other aspect of the ctorate for Informate notwithstanding an ently valid OMB cor	and maintaining his collection of ion Operations y other provision trol number.	g the data needed, and completir finformation, including suggestio and Reports (0704-0188), 1215	ng and reviewing the one of the second of th	collectio irden, to way, Su	n of informa Departmer iite 1204, Ar	ne for reviewing instructions, searching tion. Send comments regarding this burden at of Defense, Washington Headquarters lington, VA 22202-4302. Respondents should the a collection of information if it does not		
	DATE (DD-MM-		2. REPORT TYPE				3. DATES COVERED (From - To)		
22-01-2	,	,	JPL Publication				,		
4. TITLE AN	D SUBTITLE				5a.	CONTRAC	CT NUMBER		
Single Eve	ent Gate Rup	ture Chara	acterization of the Fuji N	//OSFETs:	N/	AS7-030	01		
			08P20), and NSD1A01			GRANT N			
	(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				00.	0.0.0			
						5c. PROGRAM ELEMENT NUMBER			
6. AUTHOR	(S)				5d.	PROJEC1	NUMBER		
Scheick, L					102	2197			
						TASK NU	MBFR		
						23.5			
							IT NUMBER		
					31.	WORK OR	III NOWIDEN		
7 PERFORI	MING ORGANIZ	ΔΤΙΟΝ ΝΔΜ	E(S) AND ADDRESS(ES)			8 PERF	DRMING ORGANIZATION		
	sion Laborato		2(0) / 11/2 / 12/21/200(20)			REPORT NUMBER			
•	Institute of Te	-					Publication 14-6		
		scrinology				0			
	Grove Drive								
Pasadena	, CA 91009								
National A	veronautics ar	nd Space /	Y NAME(S) AND ADDRESS Administration	S(ES)		10. SPO	NSORING/MONITOR'S ACRONYM(S)		
Washington, DC 20546-0001						11. SPONSORING/MONITORING REPORT NUMBER			
12. DISTRIB	UTION/AVAILA	BILITY STA	TEMENT			1			
Unclassifie	ed—Unlimited	t							
Subject C	ategory 33 E	lectronics	and Electrical Enginee	ring					
-					dard				
Availability: NASA CASI (301) 621-0390 Distribution: Nonstandard 13. SUPPLEMENTARY NOTES									
13. SUPPLE	IMENTART NOT	L 3							
14. ABSTRA	ACT								
			power MOSFETs for s e compared against co				GR) and single-event burnout es.		
15. SUBJEC	TTERMS								
Single-eve	ent burnout, S	SEB, metal A7M Unive	–oxide–semiconductor ersity, TAMU, Radiation	field-effect tran Effect Facility,	sisto REF	r, MOSF	ET, Fuji, single-event gate		
16 SECTION	TV CI ASSIEICA	TION OF:	17. LIMITATION	18. NUMBER OF	19	9a. NAME	OF RESPONSIBLE PERSON		
16. SECURITY CLASSIFICATION OF: a. REPORT b. ABSTRACT c. THIS PAGE			PAGES			Desk at help@sti.nasa.gov			
a. REPORT B. ABSTRACT C. THIS PAGE 1111 36				HONE NUMBER (Include area code)					
•		. –	i	Ī	, ,,				

(301) 621-0390